DERWENT-ACC-NO:

2003-893843

DERWENT-WEEK:

200530

COPYRIGHT 2007 DERWENT INFORMATION LTD

TITLE:

Method for planting flock on textile and

device thereof

INVENTOR: LEE, B G

PATENT-ASSIGNEE: LEE B G[LEEBI]

PRIORITY-DATA: 2002KR-0004175 (January 24, 2002)

PATENT-FAMILY:

PUB-NO PAGES MAIN-IPC

001 D06C 011/00

PUB-DATE LANGUAGE

KR 464136 B

January 3, 2005 N/A

000 D06C 011/00 KR 2003063833 A

July 31, 2003

APPLICATION-DATA:

PUB-NO

APPL-DESCRIPTOR APPL-NO

APPL-DATE

KR 464136B

N/A 2002KR-0004175

January 24, 2002 KR 464136B N/A

Previous Publ.

KR2003063833

KR2003063833A

N/A

2002KR-0004175

N/A

January 24, 2002

INT-CL (IPC): D06C011/00

ABSTRACTED-PUB-NO: KR2003063833A

BASIC-ABSTRACT:

NOVELTY - A method for planting flock on textile and a device thereof

characterized by planting the flock by an electrostatic adsorption

absorbing unplanted flock, going a jig from a printing unit to an absorbing

unit in order and planting the flock on a pattern part. The method and the device planting the flock are capable of reusing the flock,

2/10/07 FAST Version: 2.1.0.14

4 -----

preventing

hole: a

surroundings pollution, increasing productivity, automating a planting process,

reducing the amount of materials used and flocking various colors.

DETAILED DESCRIPTION - The planting method of the <u>flock</u> comprises the steps of:
coating a surface of the textile with a **thermosetting** adhesive on a

proper pattern to print; bonding the **flock** on the adhesive to **flock**; heat-

drying the textile bonded the <u>flock</u> and the adhesive; brushing the flock to

raise the flock; and the addressive; brushing the flock to flock; and then absorbing the unplanted flock. The planting device

of the flock is comprised of: a printing unit(10) through hole which is

formed on a screen, having proper pattern; a screen supplied with the adhesive; a

device for coating the surface with the adhesive through the through

flocking unit(20) for planting the flock on the adhesive; a heat-drying

unit(30) for heat-drying the textile; a brushing unit(50) for raising the

planted flock; and the absorbing unit(60) for absorbing the unplanted flock.

CHOSEN-DRAWING: Dwg.1/10

TITLE-TERMS: METHOD PLANT FLOCK TEXTILE DEVICE

DERWENT-CLASS: F07

CPI-CODES: F03-D03;

SECONDARY-ACC-NO:

CPI Secondary Accession Numbers: C2003-253942

C2003-233942